

# Lever gauge indicators

## Application

For measuring deviations in concentricity, axial run-out, parallelism and flatness. For centring shafts of boreholes and aligning workpieces.

## Delivery

Lever gauge probe, measuring probe with 2 mm diameter cemented carbide ball, 8 mm diameter clamping shaft for mounting on measuring stands, measuring probe wrench with case

<b>Art. no.</b>	<b>33310 060</b>
<b>Calibration Group</b>	L
<b>Scale value</b>	0.002 mm
<b>Length measuring range</b>	0.2 mm
<b>Measurement force</b>	0.15 N
<b>Measuring ball material</b>	Carbide
<b>Length of measuring sensor from centre of ball</b>	12.8 mm
<b>Ball diameter</b>	2 mm
<b>Pivot range of measuring sensor</b>	240 Degree
<b>Diameter</b>	40 mm
<b>Connection thread</b>	M1.6
<b>DIN</b>	2270

